

Vanguard Automotive Enterprises, Inc.

P.O. BOX 405 • 942 WEST LIBERTY ST. • MEDINA, OHIO 44256

725-4350

NC 2819

Mike Velton

INVOICE DATE	12/21/72
OUR ORDER NO.	
YOUR ORDER NO.	
TERMS	F. O. B.
SALESMAN	
SHIPPED VIA	

SHIPPED TO _____ PPD. OR COLL. _____

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	<u>PARTS</u>		
1	+030 Ring set	35.00	
1	Chain tensioner	1.28	
1	68x3 fitting	.52	
1	49x8 fitting	1.64	
1	P-44C expansion plug	1.25	
1	4-1 1 1/2" FF exhaust system	170.00	
		<u>209.69</u>	209.69
	<u>SPECIAL OUTSIDE SERVICES</u>		
	Bore cylinder block +.030	22.00	
	Balance 4 pistons	6.00	
	Knurl valve guides	10.00	
	Machine 099 from top of block	19.50	
	Line bore new cam bearings	16.50	
		<u>74.00</u>	74.00
	<u>SERVICES</u>		
	Rebuild 1600 Cortina to FF spec.		
	Grind & Polish inlet ports		
	Machine 5 offset cam drive pin		
	Rework carburetor linkage		
	Disassemble oil pump and lap mating surfaces & rotors.		
	Dyno services & tuning		
	Measure piston bowl volums and head to establish 10/1 CR.		
	Rework distributor		472.00
		Tax	9.42
		Total	\$765.11

Paid JPM

RACING CAR FOR NON-STREET USE
 NO INSURANCE OF ANY TYPE ISSUED — RACING AT OWNERS
 OWN RISK — THERE ARE NO EXPRESS OR IMPLIED
 WARRANTIES OF MERCHANTABILITY OR OTHERWISE.